DAILY WORK ORDER	
	Work Period: 8/26/87
Contractor: O. H. Materials Contractor Rep.: Paul Street	OSC: Jack D. Harmon
<ul> <li>1.)Clean sumps #1, #2 &amp; #3</li> <li>2.)Lasering in area #12 along w/sumps #43-46, #34 and #35</li> <li>3.)Repair sump covers as needed.</li> <li>4.)Cover the debris with visqueen &amp; secure the doorways into areas #2 and #3.</li> <li>5.)Sample area #7 1st and 2nd floors</li> </ul>	2.) () () (x) 3.) () () (x) 4.) () () (x)
	EQUIPMENT USED FROM PREVIOUS DAY:  All Authorized  COMMENTS:  (4) Porta-Johns (1) Pneumatic Forklift
PERSONNEL AUTHORIZED: (1) Response Manager (1) Laborer (1) Lab Technician (2) (8) Clean-up Technician (1)	<ul><li>(1) Foreman (3)</li><li>(2) Foreman (2)</li><li>(1) Field Clerk</li><li>(5) Clean-up Technician (2)</li><li>(1) Lab Tech. I</li></ul>
Centractor Signature:  Date: \( \lambda \lambd	OSC Signature:  Out D Hu Date: 8/26/87